

# WEST Search History

[Hide Items](#) [Restore](#) [Clear](#) [Cancel](#)

DATE: Thursday, July 21, 2005

<a href="#">Hide?</a>	<a href="#">Set Name</a>	<a href="#">Query</a>	<a href="#">Hit Count</a>
<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>			
<input type="checkbox"/>	L52	l48 same (wire or rod)	45
<input type="checkbox"/>	L51	L48 and 266/\$.ccls.	0
<input type="checkbox"/>	L50	L48 and 148/\$.ccls.	5
<input type="checkbox"/>	L49	L48 and 148/	26
<input type="checkbox"/>	L48	(uniform near tensile near strength)	265
<input type="checkbox"/>	L47	L43 and 266/78.ccls.	0
<input type="checkbox"/>	L46	L43 and 266/87.ccls.	3
<input type="checkbox"/>	L45	L43 and 148/511.ccls.	3
<input type="checkbox"/>	L44	L43 and 148/510.ccls.	1
<input type="checkbox"/>	L43	L42 and 148/\$.ccls.	670
<input type="checkbox"/>	L42	(induction near heat\$3) and (cool\$3 or quench\$3) and (temper\$3)	2760
<input type="checkbox"/>	L41	148/511.ccls.	193
<input type="checkbox"/>	L40	(wire or rod ) and 148/511.ccls	0
<input type="checkbox"/>	L39	(wire ) and 148/510.ccls	0
<input type="checkbox"/>	L38	(wire or rod) and 148/510.ccls	0
<input type="checkbox"/>	L37	L32 and 266/87.ccls.	3
<input type="checkbox"/>	L36	L32 and 266/78.ccls.	0
<input type="checkbox"/>	L35	L32 and 266/\$.ccls.	75
<input type="checkbox"/>	L34	L32 and 266/.ccls.	0
<input type="checkbox"/>	L33	L32 and 266/87.ccls.	3
<input type="checkbox"/>	L32	( wire) and (cool\$3 or quench\$3) and heat\$3 and induction and temper\$3	1744
<input type="checkbox"/>	L31	( wire) and (cool\$3 or quench\$3) and 266/87.ccls.	86
<input type="checkbox"/>	L30	( wire) and 266/87.ccls.	105
<input type="checkbox"/>	L29	( wire) and 266/103.ccls.	90
<input type="checkbox"/>	L28	l27 and 266/\$.ccls.	0
<input type="checkbox"/>	L27	(tapered near wire)	1063
<input type="checkbox"/>	L26	( wire) and (quench\$3 or cool\$3) and temper\$3 and 266/104.ccls.	28
<input type="checkbox"/>	L25	( wire) and 266/104.ccls.	114
<input type="checkbox"/>	L24	( wire) and 266/103.ccls.	90
<input type="checkbox"/>	L23	(tapered near wire) and 266/103.ccls.	0
<input type="checkbox"/>	L22	l9 and (tapered near wire)	16

█	L21	L20 and heat\$3	75
█	L20	l16 and (tensile near strength)	104
█	L19	L16 and 266/\$.ccls.	0
█	L18	L16 and 148/595.ccls.	0
█	L17	L16 and 148/576.ccls.	0
█	L16	(tapered near wire)	1063
█	L15	L9 and 148/576.ccls.	27
█	L14	L9 and 148/595.ccls.	43
█	L13	L10 and 148/595.ccls.	1
█	L12	L11 and 148/\$.ccls.	48
█	L11	L10 and induction	306
█	L10	L9 and taper\$3	2173
█	L9	wire and heat\$3 and (quench\$3 or cool\$3) and temper\$3	19343
█	L8	l5 and (uniform near tensile)	1
█	L7	l5 and 148/\$.ccls.	0
█	L6	L3 same tensile and strength	16
█	L5	L3 and tensile and strength	119
<i>DB=PGPB,USPT,USOC,EPAB; PLUR=YES; OP=OR</i>			
█	L4	L3 and (quench\$3 or cool\$3) and temper\$3	15
█	L3	(tapered near wire)	881
<i>DB=JPAB; PLUR=YES; OP=OR</i>			
█	L2	L1 same quench\$3 same temper\$3	1
█	L1	(tapered near wire)	54

END OF SEARCH HISTORY